

## Umrechnungstabelle Drücke

mbar	Micron	Torr	mm HG Vakuum
10	7516	7.5	752
5	3759	3.6	756
2	1503	1.5	758
1	752	0.75	759
0.5	376	0.36	
0.4	300	0.3	
0.3	225	0.23	
0.2	150	0.15	
0.1	75	0.08	
0.09	68		
0.07	53		
0.06	45		
0.05	38		
0.04	30		
0.03	22		
0.02	15		
0.01	8		

## Umrechnungstabelle Temperaturen

Umrechnung von °C in °F:  $^{\circ}\text{C} \times 1,8 + 32 = ^{\circ}\text{F}$

Umrechnung von °F in °C:  $(^{\circ}\text{F} - 32) : 1,8 = ^{\circ}\text{C}$

°C	°F	°C	°F	°C	°F	°C	°F
100	212	30	86	212	100	70	21
95	203	25	77	200	93	60	16
90	194	20	68	190	88	50	10
85	185	15	59	180	82	40	4
80	176	10	50	170	77	30	0
75	167	4	39	160	71	20	-7
70	158	0	32	150	66	10	-12
65	149	-10	14	140	60	0	-18
60	140	-20	-4	130	54	-10	-23
55	131	-30	-22	120	49	-20	-29
50	122	-40	-40	110	43	-30	-34
45	113	-50	-58	100	38	-40	-40
40	104	-60	-76	90	32	-50	-46
35	95			80	27	-60	-51
						-112	-80
		-273	-460			-460	-273